

Installing Millennium to Pole Instructions

Tools needed:

- 3/16th Allen wrench (supplied)

Installing the Pole into the Pole Clamp on your new Millennium

- Make sure that the pole mounting clamp is oriented correctly – the 2 preinstalled screw heads (clamping screws) that are in the pole clamp should be facing towards the front of the Millennium.
- The 2 clamping screws can be loosened if a larger gap is needed to fit the clamp over the top of the pole, allowing the 2 parts of the clamp to slide apart slightly; however do not remove these screws. This will allow easier placement of the machine onto the pole.
- Before proceeding, make sure that the pole clamp has been attached to the bottom of the T-bar on the Millennium and the screws are tight. The clamp should be flush against the T-bar without any gaps or looseness.
- Carefully lift the Millennium and place it onto the top of the pole slipping the pole into the clamp approximately three quarters to seven eights of an inch deep (3/4" – 7/8"). While confirming that the machine is now level, hold the machine in place and tighten the clamping screws.

The installed Millennium on the pole should look like this:

